



Factory gate



Factory name



Factory address



Factory GPS data



Production building



Raw materials warehouse



Printing



Die cutting



Indentation



Assembling and packing



Finished products warehouse



Safety exit sign and emergency light



Evacuation plan



Fire equipment 1



Fire equipment 2



Fire facilities inspection records



Fire alarm testing



Test for emergency light



Test for fire hydrant



amfori BSCI Code onsite




Attendance recorder



First aid kit



Toilet



Wash basin



Drinking water, there were toilet paper and liquid soap provided in the toilet




All the external covers of all electric boxes were locked



Suggestion box



PPEs warning signs




PPEs wore by the workers



Chemicals storage




Chemicals label



MSDS onsite



Eye washing equipment



NC

80% chemicals in the workshop were not equipped with secondary containments



NC

10% chemicals were not identified with safety labels, such as cleaning agent, etc.



NC

30% goods were stored against the wall